









ADDERBURY – BENCHES RECORD



	SERIAL NO:	ADD/01
LOCATION: Southern side of The Green.		
DATE ERECTED:	1977	
FRAME CONSTRUCTION:	Four legged wooden frame	
FRAME FINISH:	Oiled	
SEAT CONSTRUCTION:	Wooden seat slats with vertical wooden slat back rest	
SEAT FINISH:	Oiled	
ANY INSCRIPTIONS?	Engraving – SEE FROM THIS SEAT THREE OAKS NEW SEAT FOR THE QUEEN IN THE JUBILEE YEAR 1977	
COMMENTS ON CONDITION:	Structure is sound. Wood has become greyed with age and with minor greening.	
DATE PICTURE TAKEN AND INSPECTION MADE: 12 October 2010 MAINTENANCE RECOMMENDATION: Sand down and re-oil if deemed necessary.		



	SERIAL NO:	ADD/02
LOCATION: On the Green at the junction of High Street and Lake Walk.		
DATE ERECTED:	Unknown	
FRAME CONSTRUCTION:	Six legged metal frame	
FRAME FINISH:	Painted green	
SEAT CONSTRUCTION:	Three wooden slats / two horizontal wooden slat back rest	
SEAT FINISH:	Painted green	
ANY INSCRIPTIONS?	No	
COMMENTS ON CONDITION:	Structure is sound. Paint has become chipped and worn in places.	
DATE PICTURE TAKEN AND INSPECTION MADE: 12 October 2010 MAINTENANCE RECOMMENDATION: Sand down and re-paint (a different colour)		


	SERIAL NO:	ADD/03
LOCATION: On the Green by the bus stop on the High Street opposite The Coach & Horses.		
DATE ERECTED:	1994	
FRAME CONSTRUCTION:	Two legged metal frame	
FRAME FINISH:	Powder coated dark grey	
SEAT CONSTRUCTION:	Two wooden slats / single horizontal wooden slat back rest	
SEAT FINISH:	Oiled	
ANY INSCRIPTIONS?	Plaque: To commemorate the Centenary of ADDERBURY PARISH COUNCIL 1894 - 1994	
COMMENTS ON CONDITION:	Structure is sound. Wood has become greened with age with some lichen growth.	
DATE PICTURE TAKEN AND INSPECTION MADE: 12 October 2010 MAINTENANCE RECOMMENDATION: Sand down and re-oil if deemed necessary.		



	SERIAL NO:	ADD/04
LOCATION: At the bus stop on the corner of High Street and Chapel Lane.		
DATE ERECTED:	Unknown	
FRAME CONSTRUCTION:	Four legged wooden frame	
FRAME FINISH:	Oiled	
SEAT CONSTRUCTION:	Wooden seat slats with vertical wooden slat back rest	
SEAT FINISH:	Oiled	
ANY INSCRIPTIONS?	No	
COMMENTS ON CONDITION:	Structure is sound. Wood has greyed with little/no lichen growth.	
DATE PICTURE TAKEN AND INSPECTION MADE: 12 October 2010 MAINTENANCE RECOMMENDATION: Sand down and re-oil if deemed necessary.		



	SERIAL NO:	ADD/05
LOCATION: Along the main path through the Lucy Placket playing field.		
DATE ERECTED:	Unknown	
FRAME CONSTRUCTION:	Six legged metal frame	
FRAME FINISH:	Painted blue/green	
SEAT CONSTRUCTION:	Horizontal metal slats for seat and back rest	
SEAT FINISH:	Painted blue/green	
ANY INSCRIPTIONS?	No	
COMMENTS ON CONDITION:	Structure is generally sound but some seat slats are bent. Some rust patches and lichen growth.	
DATE PICTURE TAKEN AND INSPECTION MADE: 12 October 2010 MAINTENANCE RECOMMENDATION: Straighten bent seat slats. Sand blast old paint and rust and then prime and repaint. OR REPLACE.		

	SERIAL NO:	ADD/06
LOCATION: Along the main path through the Lucy Placket playing field.		
DATE ERECTED:	Unknown	
FRAME CONSTRUCTION:	Six legged metal frame	
FRAME FINISH:	Painted blue/green	
SEAT CONSTRUCTION:	Horizontal metal slats for seat and back rest	
SEAT FINISH:	Painted blue/green	
ANY INSCRIPTIONS?	No	
COMMENTS ON CONDITION:	The front right leg of the bench has broken off. Some rust patches and lichen growth.	
DATE PICTURE TAKEN AND INSPECTION MADE: 12 October 2010 MAINTENANCE RECOMMENDATION: Weld on new metal leg. Sand blast old paint and rust and then prime and repaint. OR REPLACE.		



	SERIAL NO:	ADD/07
LOCATION: Along the main path through the Lucy Placket playing field.		
DATE ERECTED:	Unknown	
FRAME CONSTRUCTION:	Six legged metal frame	
FRAME FINISH:	Painted blue/green	
SEAT CONSTRUCTION:	Horizontal metal slats for seat and back rest	
SEAT FINISH:	Painted blue/green	
ANY INSCRIPTIONS?	No	
COMMENTS ON CONDITION:	Structure is generally sound but some seat slats are bent. Some rust patches and lichen growth.	
DATE PICTURE TAKEN AND INSPECTION MADE: 12 October 2010 MAINTENANCE RECOMMENDATION: Straighten bent seat slats. Sand blast old paint and rust and then prime and repaint. OR REPLACE.		

	SERIAL NO:	ADD/08
LOCATION: Along the main path through the Lucy Placket playing field.		
DATE ERECTED:	Unknown	
FRAME CONSTRUCTION:	Six legged metal frame	
FRAME FINISH:	Painted green	
SEAT CONSTRUCTION:	Horizontal metal slats for seat and back rest	
SEAT FINISH:	Painted green	
ANY INSCRIPTIONS?	Brass plaque:	
COMMENTS ON CONDITION:	Structure is sound.	
DATE PICTURE TAKEN AND INSPECTION MADE: 12 October 2010 MAINTENANCE RECOMMENDATION: Nil.		



	SERIAL NO:	ADD/09
LOCATION: Along the main path through the Lucy Placket playing field.		
DATE ERECTED:	Unknown	
FRAME CONSTRUCTION:	Eight legged metal frame	
FRAME FINISH:	Painted blue/green	
SEAT CONSTRUCTION:	Horizontal metal slats for seat and back rest	
SEAT FINISH:	Painted blue/green	
ANY INSCRIPTIONS?	Brass plaque:	
COMMENTS ON CONDITION:	Structure is generally sound but some seat slats are bent. Some rust patches and lichen growth.	
DATE PICTURE TAKEN AND INSPECTION MADE: 12 October 2010 MAINTENANCE RECOMMENDATION: Straighten bent seat slats. Sand blast old paint and rust and then prime and repaint. Repair damaged front left leg. OR REPLACE.		

	SERIAL NO:	ADD/10
LOCATION: At the junction of Round Close Road and Dog Close with Cross Hill Road – opposite the bus stop shelter.		
DATE ERECTED:	Unknown	
FRAME CONSTRUCTION:	Six legged wooden frame	
FRAME FINISH:	Oiled	
SEAT CONSTRUCTION:	Horizontal wooden slats for seat and vertical for back rest	
SEAT FINISH:	Oiled	
ANY INSCRIPTIONS?	No	
COMMENTS ON CONDITION:	Structure is generally sound but supporting cross spar at bottom has broken on left hand side. Wood has become greyed with age and with minor greening.	
DATE PICTURE TAKEN AND INSPECTION MADE: 12 October 2010 MAINTENANCE RECOMMENDATION: Replace cross spar. Sand down and re-oil if deemed necessary.		



	SERIAL NO:	ADD/11
LOCATION: At the junction of Manor Road with Horn Hill Road. PRIVATE OWNERSHIP?		
DATE ERECTED:	2007	
FRAME CONSTRUCTION:	Four legged metal frame	
FRAME FINISH:	Painted green	
SEAT CONSTRUCTION:	Horizontal metal slats for seat and two for back rest	
SEAT FINISH:	Painted green	
ANY INSCRIPTIONS?	Plaque: In Loving Memory of MONA CHARLOTTE FIELD 6.8.1910 – 21.3.2007	
COMMENTS ON CONDITION:	Structure is sound.	
DATE PICTURE TAKEN AND INSPECTION MADE: 12 October 2010 MAINTENANCE RECOMMENDATION: Nil.		

	SERIAL NO:	ADD/12
LOCATION: Underneath the oak tree at the junction of Milton Road, Berry Hill Road and Horn Hill Road.		
DATE ERECTED:	Unknown	
FRAME CONSTRUCTION:	Two legged metal frame	
FRAME FINISH:	Powder coated black	
SEAT CONSTRUCTION:	Horizontal wooden slats for seat and one for back rest	
SEAT FINISH:	Oiled	
ANY INSCRIPTIONS?	No	
COMMENTS ON CONDITION:	Structure is sound. Wood is greyed with minor greening.	
DATE PICTURE TAKEN AND INSPECTION MADE: 12 October 2010 MAINTENANCE RECOMMENDATION: Sand down and re-oil if deemed necessary.		

	SERIAL NO:	ADD/13
LOCATION: Adderbury cemetery.		
DATE ERECTED:	Unknown	
FRAME CONSTRUCTION:	Six legged metal frame	
FRAME FINISH:	Painted blue/green	
SEAT CONSTRUCTION:	Horizontal metal slats for seat and for back rest	
SEAT FINISH:	Painted blue/green	
ANY INSCRIPTIONS?	No	
COMMENTS ON CONDITION:	Structure is generally sound. A bolt on one horizontal slat on the back rest has broken. Paint is chipped with minor rusting.	
DATE PICTURE TAKEN AND INSPECTION MADE: 12 October 2010 MAINTENANCE RECOMMENDATION: Replace bolt on slat. Sand blast old paint and rust and then prime and repaint.		

	SERIAL NO:	ADD/14
LOCATION: Adderbury cemetery. PRIVATE OWNERSHIP?		
DATE ERECTED:	2006	
FRAME CONSTRUCTION:	Four legged wooden frame	
FRAME FINISH:	Stained brown	
SEAT CONSTRUCTION:	Horizontal wooden slats for seat and vertical for back rest	
SEAT FINISH:	Stained brown	
ANY INSCRIPTIONS?	Plaque: This seat is dedicated to the memory of my lovely wife Dilys Shillito who fell asleep 27-12-06 aged 79 years	
COMMENTS ON CONDITION:	Structure is sound. Staining has been badly weathered in places.	
DATE PICTURE TAKEN AND INSPECTION MADE: 12 October 2010 MAINTENANCE RECOMMENDATION: Re-stain if deemed necessary.		

	SERIAL NO:	ADD/15
LOCATION: Adderbury Lakes. PRIVATE OWNERSHIP?		
DATE ERECTED:	2007	
FRAME CONSTRUCTION:	Four legged wooden frame	
FRAME FINISH:	Oiled	
SEAT CONSTRUCTION:	Horizontal wooden slats for seat and back rest	
SEAT FINISH:	Oiled	
ANY INSCRIPTIONS?	Engraving: "I WOULDN'T CHANGE A THING" RUPERT CARR 28 NOV 1981 – 15 NOV 2007	
COMMENTS ON CONDITION:	Structure is sound and in good condition. Wood has greyed slightly.	
DATE PICTURE TAKEN AND INSPECTION MADE: 12 October 2010 MAINTENANCE RECOMMENDATION: Nil		



	SERIAL NO:	ADD/16
LOCATION: Griffin Close.		
DATE ERECTED:	Unknown	
FRAME CONSTRUCTION:	Two legged wooden frame	
FRAME FINISH:	Oiled	
SEAT CONSTRUCTION:	Horizontal wooden slats for seat and back rest	
SEAT FINISH:	Oiled	
ANY INSCRIPTIONS?	Nil	
COMMENTS ON CONDITION:	Structure is sound and in good condition. Wood has greyed slightly.	
DATE PICTURE TAKEN AND INSPECTION MADE: 09 November 2010 MAINTENANCE RECOMMENDATION: Sand down and re-oil if deemed necessary.		

	SERIAL NO:	ADD/17
LOCATION: Summers Close.		
DATE ERECTED:	Unknown	
FRAME CONSTRUCTION:	Two legged metal frame	
FRAME FINISH:	Painted black	
SEAT CONSTRUCTION:	Horizontal wooden slats for seat and back rest	
SEAT FINISH:	Oiled	
ANY INSCRIPTIONS?	Nil	
COMMENTS ON CONDITION:	Structure is sound and in good condition. Wood has greyed slightly.	
DATE PICTURE TAKEN AND INSPECTION MADE: 09 November 2010 MAINTENANCE RECOMMENDATION: Nil.		

	SERIAL NO:	ADD/18
LOCATION: Summers Close.		
DATE ERECTED:	Unknown	
FRAME CONSTRUCTION:	Two legged metal frame	
FRAME FINISH:	Painted black	
SEAT CONSTRUCTION:	Horizontal wooden slats for seat and back rest	
SEAT FINISH:	Oiled	
ANY INSCRIPTIONS?	Nil	
COMMENTS ON CONDITION:	Structure is sound and in good condition. Wood has greyed slightly.	
DATE PICTURE TAKEN AND INSPECTION MADE: 09 November 2010 MAINTENANCE RECOMMENDATION: Nil.		

	SERIAL NO:	ADD/19
LOCATION: Falkner's Close.		
DATE ERECTED:	Unknown	
FRAME CONSTRUCTION:	Four legged metal frame	
FRAME FINISH:	Painted black	
SEAT CONSTRUCTION:	Horizontal wooden slats for seat and back rest	
SEAT FINISH:	Oiled	
ANY INSCRIPTIONS?	Nil	
COMMENTS ON CONDITION:	Structure is sound and in very good condition.	
DATE PICTURE TAKEN AND INSPECTION MADE: 09 November 2010 MAINTENANCE RECOMMENDATION: Nil.		

	SERIAL NO:	ADD/20
LOCATION: Falkner's Close.		
DATE ERECTED:	Unknown	
FRAME CONSTRUCTION:	Four legged metal frame	
FRAME FINISH:	Painted black	
SEAT CONSTRUCTION:	Horizontal wooden slats for seat and back rest	
SEAT FINISH:	Oiled	
ANY INSCRIPTIONS?	Nil	
COMMENTS ON CONDITION:	Structure is sound and in very good condition.	
DATE PICTURE TAKEN AND INSPECTION MADE: 09 November 2010 MAINTENANCE RECOMMENDATION: Nil.		

	SERIAL NO:	ADD/21
LOCATION: Corner of Aynho Road and A4260 Banbury Road.		
DATE ERECTED:	1981	
FRAME CONSTRUCTION:	Four legged wooden frame	
FRAME FINISH:	Oiled	
SEAT CONSTRUCTION:	Horizontal wooden slats for seat and vertical for back rest	
SEAT FINISH:	Oiled	
ANY INSCRIPTIONS?	Plaque: BANBURY HOMES & GARDENS Presented by Banbury Homes & Gardens Limited 1981	
COMMENTS ON CONDITION:	Structure is sound and in good condition. Wood is greyed with some greening visible.	
DATE PICTURE TAKEN AND INSPECTION MADE: 09 November 2010 MAINTENANCE RECOMMENDATION: Sand down and re-oil if deemed necessary.		

	SERIAL NO:	ADD/22
LOCATION: Adderbury Court Amenity Area.		
DATE ERECTED:	Unknown	
FRAME CONSTRUCTION:	Two legged metal frame	
FRAME FINISH:	Painted green	
SEAT CONSTRUCTION:	Horizontal wooden slats for seat and back rest	
SEAT FINISH:	Oiled	
ANY INSCRIPTIONS?	Nil	
COMMENTS ON CONDITION:	Structure is sound and in generally good condition. Wood is greyed with some greening visible. Some graffiti scratched into surface. Metalwork rusted in places.	
DATE PICTURE TAKEN AND INSPECTION MADE: 17 November 2010 MAINTENANCE RECOMMENDATION: Sand down wood and re-oil if deemed necessary. Prime and paint repaint metalwork.		

